



1	2	3	4	5	6
Main supply		Main Fuses	Contactor, pump	Contactor seal	
L1 L2		F1 + F2	K1	K2	
			Motor	Seal transformer	
			M1	TR1	






in power supply
1-2
MD
10-2003

1	2	3	4	5	6
Main supply		Main Fuse	Contactor, pump	Contactor seal	
L1 L2		F1	K1	K2	
			Motor	Seal transformer	
			M1	TR1	



in power supply
1-2
MD
06-2001



eumatic diagrams
1-1
MD
06-2004

www.Gastro-Star.at