



1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Input	Input	COM	Microswitch		Pump		CO2	Seal	Seal		Soft-air	De-vac	Input	Input
0 Volts	24 Volts				Contactor		Valve	Valve	Contactor		Valve	Valve	0 Volts	9 Volts
	Fuse				K1		Y2	Y3	K2		Y4	Y5		Fuse
	F1													F2




1 V, 9 V	Boxer Series
2-2	100-230 V - 1 ~ - 50/60 Hz
MD	
06-2001	

1	2	3	4	5	6
Main supply		Main Fuses	Contactor pump	Contactor seal	
L1 L2		F1 + F2	K1	K2	
			Motor	Seal transformer	
			M1	TR1	




in power supply
1-2
MD
10-2003

1	2	3	4	5	6
Main supply		Main Fuse	Contactor pump	Contactor seal	
L1 L2		F1	K1	K2	
			Motor	Seal transformer	
			M1	TR1	



in power supply
1-2
MD
06-2001



eumatic diagrams
1-1
MD
06-2004

www.Gastro-Star.at